



**NOTE:** Wire dimming conductors as Class 1

### 1 REMOTE DRIVER BOX

Please refer to the remote driver installation sheet for more informations.




### 2




Connect the fixture cable (A) to the main power (B) and fix crossbar (C) to the junction box (D) with screws.

### 3




Fix the canopy (E) onto the crossbar (C) with screws.

### 4




Install the threaded adapter (F) onto the canopy (E) with screws.

### 5



Thread the fixture (G) onto the threaded adapter (F).

### 6



Secure the fixture (G) onto the canopy (E) with the set screw (H).