



NOTE: Wire dimming conductors as Class 1

1 SINGLE FIXTURE




Locate ceiling mounting points according to supplied client drawing. Make a knot in the power cord (A) and then connect it to the ceiling power feed. Install cross bar to the junction box.

2 POWER SIDE




Secure canopy (B) with grip lock (C) on threaded rod (D).

3 NON-POWER SIDE




Secure canopy (E) with cable coupler (F) on threaded rod (G) (by other).

4




Insert the aircraft cable (H) into the griplock after unscrewing the safety nut (I). Secure the power cord (A) to the aircraft cable with the plastic clip (J). Make final adjustments of the cable (H) and tighten the safety nut onto the griplock.

5 CONTINUOUS SYSTEM









For a continuous system, repeat steps 1 to 3 for all mounting.

6



Remove the top lens (K) of the second fixture (L) with the included lens tool.



13

