



SURFACE MOUNT DIRECT MOUNT - INSTALLATION INSTRUCTIONS



NOTE: Wire dimming conductors as Class 1





Locate the place the fixutre will be installed and make a 7/8" dia hole for the power cable to pass. Install the Threaded Adpater plate (A) with the screws where the hole was made.

