



NOTE: Wire dimming conductors as Class 1

1




Fix crossbar (A) to the junction box (B) with screws.

2




Fix the canopy (C) onto the crossbar (A) with screws.

3



Make wire connection between main power (D) and the fixture (E).

4



Fix the fixture (F) onto the canopy and adapter (G). Lock it in place with set screws (H).